

Kerr-McGee Oil & Gas OnShore LP A subsidiary of Anadarko Petroleum Corporation 1099 18th Street Denver, CO 80202 (720) 929-6000

November 5, 2015

Town of Erie 645 Holbrook St. P.O. Box 750 Erie, CO 80516 Attn: R. Martin Ostholthoff

Re: Notice of Intent to Plug and Abandon existing Oil and Gas Well

Dear Mr. Ostholthoff:

This is a courtesy notice to make the Town of Erie aware of our intent to plug and abandon an oil and gas well that, is located within Erie's municipal boundary. We feel it is important to send notification in the event questions should arise. Kerr-McGee Oil & Gas Onshore LP (KMG) plans to perform these operations on the following existing oil and gas well.

CHAMPLIN 31-10 #3

05-013-08822

Section 10: T1N-R68W: NWNE

Prior to the initiation of operations we will notify residences within a half mile of the location on the timing and details of the upcoming activity.

We take pride at KMG in being a responsible operator and look forward to maintaining a long standing cooperative relationship with the Town of Erie and its residents. If you should you have any questions, regarding the plugging and abandonment of the well(s), please do not hesitate to contact me at 720-929-6321.

Thank you for your time and attention to this matter.

Sincerely,

Kerr-McGee Oil & Gas OnShore LP

Patty Varra

Municipal Planning Analyst

FORM 6 Rev 12/05

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES

Document Number:

400920926

Date Received:

10/20/2015

WELL ABANDONMEN	IT REPORT
-----------------	-----------

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval attent that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120 Contact Name: CHERYL LIGHT Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP Phone: (720) 929-6461 Address: P O BOX 173779 Fax: (720) 929-7461 City: **DENVER** State: CO Zip: 80217-Email: CHERYL.LIGHT@ANADARKO.COM For "Intent" 24 hour notice required, Name: Peterson, Tom (303) 815-9641 Email: tom.peterson@state.co.us **COGCC** contact: **API Number** 05-123-08822-00 Well Name: CHAMPLIN 31-10 Well Number: 3 Location: QtrQtr: NWNE Section: 10 Township: 1N Range: 68W Meridian: County: WELD Federal, Indian or State Lease Number: Field Name: SPINDLE Field Number: 77900 Notice of Intent to Abandon
 Subsequent Report of Abandonment
 Subsequent Report Repo Only Complete the Following Background Information for Intent to Abandon Latitude: 40.071219 Longitude: -104.986931 GPS Data: Date of Measurement: 04/01/2010 PDOP Reading: 2.3 GPS Instrument Operator's Name: Paul Tappy Reason for Abandonment: Dry X Production for Sub-economic Mechanical Problems Other Casing to be pulled: X Yes No Estimated Depth: Fish in Hole: Yes X No If yes, explain details below Weilbore has Uncemented Casing leaks: Yes X No If yes, explain details below Details: **Current and Previously Abandoned Zones Formation** Perf. Top Perf. Btm Abandoned Date Method of Isolation Plug Depth SHANNON 5180 5200 SUSSEX 4683 4755 Total: 2 zone(s)

Casing History								
Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	613	500	613	0	VISU
1ST	7+7/8	5+1/2	15.5/14	5,338	450	5,338	4,125	CALC

Pluggii	ng Procedure	for Intent	and Subsec	uent Rep	ort
CIBP #1: Depth5120 with	2 sacks cmt on top. CIPB #2: Depth			with	sacks cmt on top.
CIBP #3: Depth with				with	sacks cmt on top.
CIBP #5: Depth with	sacks c	mt on top.	-		NOTE: Two(2) sacks cement required on all CIBPs.
Set sks cmt from	ft. to	ft.	Plug Type:		Plug Tagged:
Set sks cmt from	ft. to	ft.	Plug Type:		Plug Tagged:
Set sks cmt from	ft. to	ft.	Plug Type:		Plug Tagged:
Set sks cmt from	ft. to	ft.	Plug Type:		Plug Tagged:
Set sks cmt from	ft. to	ft.	Plug Type:		Plug Tagged:
Perforate and squeeze at 4683	ft. with 85	sacks. Lea	ave at least 100 ft. i	n casing	4650 CICR Depth
Perforate and squeeze at	ft. with	sacks. Lea	ave at least 100 ft. i	n casing	CICR Depth
Perforate and squeeze at	ft. with	sacks. Lea	ave at least 100 ft. i	_	CICR Depth (Cast Iron Cement Retainer Depth)
Set 410 sacks half in, half	out surface casing f	rom 1350	ft to		. ,
Set 25 sacks at surface	out surface casing in	10111	ft. to 510 ft	Plug I	agged:
Cut four feet below ground level, we	ald on plato Ak	aoya Graund Di	ry-Hole Marker:	Von	₩ No
Set sacks in rat hole	eid on plate At	Set	sacks in m		▼ No
Casing Recovered: ft. c *Wireline Contractor:	itional Plugging I	n casing	Plugging D *Cementing Contra	Pate:	
Type of Cement and Additives Used:					*
Flowline/Pipeline has been abandone	ed per Rule 1103	Yes	No	,	*ATTACH JOB SUMMARY
Technical Detail/Comments:					
I hereby certify all statements made i	n this form are, to th	e best of my kn	nowledge, true, corr	ect. and comp	lete
Signed:		· ·	int Name: CHERY		, 6, 6,
Title: SR. REGULATORY ANALYST Date: 10/20/2015 Email: DJREGULATORY@ANADARKO.COM					
Based on the information provided horders and is hereby approved.					
COGCC Approved: JENKINS, S	EVE			Date	e: <u>11/3/2015</u>
CONDITIONS OF APPROVAL, IF A	NY:		E	Expiration Date	e: 5/2/2016
COA Type	Description				
Note changes to plugging procedure: 1) Provide 48 hour notice of plugging MIRU via electronic Form 42. 2) For 1350' plug: pump plug and displace. If surface casing plug is not circulated to surface then tag plug – must be 513' or shallower and provide 10 sx plug at the surface. Leave at least 100' cement in the casing for each plug. 3) Properly abandon flowlines as per Rule 1103. File electronic Form 42 once abandonment complete.					

Att Doc Num Name 400920926 FORM 6 INTENT SUBMITTED 400920927 PROPOSED PLUGGING PROCEDURE 400920928 WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

User Group	Comment	Comment Date
Permit	Well Completion Report dated 12/17/1976	10/23/2015 3:18:23 PM
Public Room	Document verification complete 10/22/15	10/22/2015 9:49:04 AM

Total: 2 comment(s)